



Brand:	BMW	Mileage(km):	283838
Model:	M550	Number of doors:	5
Model type:	M550xd	Vehicle length (cm):	
License plate:	XT873Z	Vehicle width (cm):	
Report code:	5787	Vehicle height (cm):	
Chassis number:	WBAMY91030C775787	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	20/12/2012	Power(kw):	280
First NL reg.:	20/03/2019	Transmission	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):	2065	Displacement(cc):	2993
Empty weight(kg):	1965	Number of cylinders:	6
Wheelbase (cm)(cm):	297	Fuel type:	Diesel
Top speed (km/h):	250	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.2	EU category:	Euro 6
Cons. outside the city (l/100 km):	6	Energy label:	D
Average consumption (l/100 km):	6.4	NL Tax Rate %:	22
Acceleration (s):	4.9	CO2 (g/km):	169
Cargo space (l):	2065	Nb. of Axles:	
Perm. max weight (kg):	2570	APK date:	31/01/2021

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	245/35 R20	Michelin	5
Tire left rear	Summer	Alloy	275/30 R20	Michelin	6
Tire right front	Summer	Alloy	245/35 R20	Michelin	5
Tire right rear	Summer	Alloy	275/30 R20	Michelin	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

☒ Not acceptable



Front bumper - Dent

Damages

Acceptable



Front left rim - Scratch



Rear left rim - Scratch



Rear bumper - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Right outside mirror - Paint repair



Front left screen - Paint repair



Front bumper - Scratch



Front bumper - Stone chippings



Front bumper - Paint repair



Left outside mirror - Paint repair



Bonnet - Stone chippings

Extra options



stoelverwarming achterin





